



BPL Presentation for CORF

25 April 2007

Jim Mollenkopf, CURRENT Group



Agenda

Overview of BPL

Basic Network Architecture

Overview of Potential Interference Issues

Benefits of BPL – Why Does Anyone Care?

Q&A


CURRENT Solutions - What BPL Can Do

Smart Grid Solutions




Solutions For:
Smart Metering
Customer Energy Management
Distribution Management
Substation Connectivity

Retail Broadband Services



Services For:
Smart Consumer
Up to 10 Mbps Broadband
Symmetric Service Offering
VoIP





Pole Assembly
 haul-Point® Pole Assembly
 IIRD Assembly

CURRENT URD System




CURRENT OH System




Network Overview

"Toolbox" Solution for Design



Frequency view of the CURRENT system on medium- and low-voltage lines



Use of HF frequencies avoided on MV lines

What About Interference?

BPL power limits set by FCC Part 15 limits

- Limits same as millions of other devices
- Verification must be done in situ
- Limits extremely low – nanowatts of radiated power
- Any resultant interference must be resolved by BPL operator

FCC BPL Report and Order provides special protection to RA sites

- Consultation areas around VLBA sites for both OH and UG for 73.0 – 74.6 MHz
- Consultation areas around specified RA sites for 1.7-38.25 MHz
- Establishes special interference mitigation requirements for BPL equipment
- Requires Certification for BPL equipment

CURRENT BPL Has Strong Track Record of Deployment Without Interference Issues

CURRENT's Approach to Interference

- Avoidance is most effective mitigation technique
- Only one device on a link transmits at a time
- Two largest BPL deployments in North America
 - Cincinnati, OH and Dallas/Ft. Worth, TX
- Zero interference complaints

No Interference Complaints of Any Kind In Any CURRENT Deployments

- No amateur radio complaints
- No broadcast radio complaints
- No public safety complaints (273 licensees within 10 miles of our Cincinnati deployment)

CURRENT Equipment is FCC Certified

- Not experimental or operating under temporary authorization

Distribution Monitoring Outage Notification Process



Old Way




2

Customer calls outage in
and Operations Center
receives notification

1

Tree falls on line
causing a feeder
outage

New Way




2

BPL dying gasp sends
notification to outage
management system



3

Dispatcher notifies field
technician who inspects entire
feeder for outage source



3

Disruption location pinpointed
and field technicians dispatched
to location of fault

Distribution Monitoring Case Study – Neutral Failure

E-Mail
Notification →

This Message is automatically generated. Do not reply to this email.

Click [here](#) to view the Secondary Neutral Failure Report for 12/10/2006 - 12/11/2006.

Thank you,
Smart Grid Support



Report →

currentlook
Smart Grid Services

Secondary Neutral Failure Report

Service Area: ABRRD 0001, GAVSW 0001, GAVSW 0007

Start Date: December 2006 End Date: December 2006

Day	Sun	Mon	Tue	Wed	Thu	Fri	Sat
≥ 26	27	28	29	30	1	2	≥ 26
≥ 3	4	5	6	7	8	9	≥ 3
≥ 10	11	12	13	14	15	16	≥ 10
≥ 17	18	19	20	21	22	23	≥ 17
≥ 24	25	26	27	28	29	30	≥ 24
≥ 31	1	2	3	4	5	6	≥ 31

Voltage Difference (V): 16 Range from 2x Nominal (V): 12

Failure Duration (seconds): 5

Run Report

Voltage Difference: The value in Volts that the two voltage legs must differ to trigger the report.
Range from 2x Nominal: The value in Volts that the sum of the two voltage legs must come to twice nominal to trigger the report.
Failure Duration: The time in seconds that the voltage difference must persist to trigger the report.

Report Start: 12/10/2006 12:00:00 AM
Report End: 12/11/2006 11:59:59 PM

Transformer	Time of Failure	Leg 1 Voltage (V)	Leg 2 Voltage (V)	Delta V
1226291	12/10/2006 1:34:29 PM	132.611	115.261	17.350

currentlook
Smart Grid Services

Voltage: kWh

Logout

Transformer Properties

ID: 1226291	Voltage: KVA:
Type: Pole: 05N03E-00334	Prot: Note: Premises: 15


Date/Time LV 1 LV 2

2006-12-07 00:00:00	124.013	123.051
2006-12-07 00:02:27	124.522	
2006-12-07 00:05:24	125.268	
2006-12-07 00:07:13	123.989	
2006-12-07 00:07:35	125.361	
2006-12-07 00:15:02	124.070	
2006-12-07 00:49:06	125.334	
2006-12-07 01:04:08	125.814	
2006-12-07 01:13:23	124.469	
2006-12-07 01:31:02	125.864	
2006-12-07 01:39:41	124.535	
2006-12-07 03:17:45	125.827	
2006-12-07 04:02:13	124.560	
2006-12-07 04:29:40	124.080	
2006-12-07 04:53:18	125.341	
2006-12-07 05:39:21	125.824	
2006-12-07 06:11:14	126.625	
2006-12-07 10:12:33	125.358	
2006-12-07 10:40:23	124.544	
2006-12-07 11:03:46	125.845	
2006-12-07 11:04:23	126.638	
2006-12-07 11:25:59	125.354	
2006-12-07 11:42:06	124.565	
2006-12-07 12:02:30	123.990	
2006-12-07 12:12:40	123.292	
2006-12-07 12:17:40	124.651	
2006-12-07 12:18:24	125.305	


Mean Minimum Maximum

LV 1: 125.285	120.920	131.904
LV 2: 124.380	117.734	127.517

Voltage for device 1226291 between 2006/12/07 and 2006/12/09




What
happened
here?



Distribution Monitoring

Case Study – Neutral Failure

“During our field investigation a loose split bolt connection was found. The bad connection was between the 2/0 and #4 copper neutral”



Voltage Data Before / After Repair





Photo of Connection

Distribution Monitoring

Case Study - Transient Secondary Fault



Investigation Trigger:
Current Look Low
Voltage Notification

Distribution Monitoring

Case Study - Transient Secondary Fault



Detailed Findings

“This is a 37.5 KVA, 120/240v transformer with 2/0 copper conductor connecting it to the secondary bus. One conductor had rubbed against the cooling fin of the transformer and burned the conductor for about 10” back to the secondary bushing of the transformer. This leg was carrying no load at the time that it was checked.

Charred cooling fin of transformer



Thank You!

